

NOTICE OF DETERMINATION OF MARKET ADMINISTRATOR

Dated:

4 May 2012

**Breach notice
identifying
number:**

2011-036(09/12/EGC30702)	2011-228(10/6/TTK30601)
2011-036(09/12/IGW11901)	2011-228(10/6/WHK32101)
2011-036(09/12/KPA12401)	2011-228(10/6/WTR12001)
2011-036(09/12/OKU16701)	2011-266(10/7/GTH11301)
2011-036(09/12/PTR32601)	2011-266(10/7/IGW11901)
2011-036(09/12/STR10201)	2011-266(10/7/KPA12401)
2011-036(09/12/TKR19701)	2011-266(10/7/OKA13201)
2011-036(09/12/TPK33301)	2011-266(10/7/OKU16701)
2011-036(09/12/WHK32101)	2011-266(10/7/OPK13001)
2011-036(09/12/WTR12001)	2011-266(10/7/PTA20901)
2011-058(10/1/EGC30702)	2011-266(10/7/PTR32601)
2011-058(10/1/ELM12301)	2011-266(10/7/STR10201)
2011-058(10/1/KPA12401)	2011-266(10/7/TAU07001)
2011-058(10/1/OKU16701)	2011-299(10/8/ELM12301)
2011-058(10/1/OPK13001)	2011-299(10/8/IGW11901)
2011-058(10/1/OPO32001)	2011-299(10/8/KPA12401)
2011-058(10/1/STR10201)	2011-299(10/8/OKA13201)
2011-058(10/1/TKR19701)	2011-299(10/8/OPK13001)
2011-058(10/1/TPK33301)	2011-299(10/8/OPO32001)
2011-058(10/1/WHK32101)	2011-299(10/8/PTA20901)
2011-058(10/1/WTR12001)	2011-299(10/8/STR10201)
2011-090(10/2/ELM12301)	2011-299(10/8/TTK30601)
2011-090(10/2/GMM08001)	2011-336(10/9/HWA20801)
2011-090(10/2/KPA12401)	2011-336(10/9/KAW04405)
2011-090(10/2/OPO32001)	2011-336(10/9/KPA12401)
2011-090(10/2/STR10201)	2011-336(10/9/OKA13201)
2011-090(10/2/TPK33301)	2011-336(10/9/OKU16701)
2011-090(10/2/TTK30601)	2011-336(10/9/PTA20901)
2011-090(10/2/WHK32101)	2011-336(10/9/TKR19701)
2011-090(10/2/WTR12001)	2011-336(10/9/TPK33301)
2011-109(10/3/ELM12301)	2011-366(10/10/ELM12301)
2011-109(10/3/GMM08001)	2011-366(10/10/HWA20801)
2011-109(10/3/GTH11301)	2011-366(10/10/KAW04405)
2011-109(10/3/GTT07701)	2011-366(10/10/KPA12401)
2011-109(10/3/HWA20801)	2011-366(10/10/OKA13201)
2011-109(10/3/IGW11901)	2011-366(10/10/OKU16701)
2011-109(10/3/KPA12401)	2011-366(10/10/PTA20901)
2011-109(10/3/NPL12101)	2011-366(10/10/TIR33502)
2011-109(10/3/OKU16701)	2011-366(10/10/TKR19701)

2011-109(10/3/OPO32001)	2011-366(10/10/TPK33301)
2011-109(10/3/STR10201)	2012-006(10/11/EGC30702)
2011-109(10/3/TAU07001)	2012-006(10/11/GMM08001)
2011-109(10/3/TPK33301)	2012-006(10/11/GTH11301)
2011-109(10/3/TTK30601)	2012-006(10/11/HWA20801)
2011-109(10/3/WHK32101)	2012-006(10/11/IGW11901)
2011-109(10/3/WTR12001)	2012-006(10/11/KAW04405)
2011-152(10/4/ELM12301)	2012-006(10/11/KPA12401)
2011-152(10/4/GTT07701)	2012-006(10/11/OKA13201)
2011-152(10/4/HWA20801)	2012-006(10/11/OKU16701)
2011-152(10/4/IGW11901)	2012-006(10/11/PTA20901)
2011-152(10/4/KAW04405)	2012-006(10/11/PTR32601)
2011-152(10/4/KPA12401)	2012-006(10/11/STR10201)
2011-152(10/4/NPL12101)	2012-006(10/11/TAU07001)
2011-152(10/4/OKU16701)	2012-006(10/11/TIR33502)
2011-152(10/4/ROT08101)	2012-006(10/11/TKR19701)
2011-152(10/4/STR10201)	2012-006(10/11/TTK30601)
2011-152(10/4/TAU07001)	2012-006(10/11/WHK32101)
2011-152(10/4/TPK33301)	2012-006(10/11/WTR12001)
2011-152(10/4/WHK32101)	2012-034(10/12/EGC30702)
2011-152(10/4/WTR12001)	2012-034(10/12/ELM12301)
2011-182(10/5/ELM12301)	2012-034(10/12/GTH11301)
2011-182(10/5/GMM08001)	2012-034(10/12/HWA20801)
2011-182(10/5/GTH11301)	2012-034(10/12/IGW11901)
2011-182(10/5/HWA20801)	2012-034(10/12/KAW04405)
2011-182(10/5/IGW11901)	2012-034(10/12/KPA12401)
2011-182(10/5/KAW04405)	2012-034(10/12/OKA13201)
2011-182(10/5/KPA12401)	2012-034(10/12/OPK13001)
2011-182(10/5/OKU16701)	2012-034(10/12/PTA20901)
2011-182(10/5/OPO32001)	2012-034(10/12/STR10201)
2011-182(10/5/PTA20901)	2012-034(10/12/TAU07001)
2011-182(10/5/PTR32601)	2012-034(10/12/TIR33502)
2011-182(10/5/TAU07001)	2012-034(10/12/TKR19701)
2011-182(10/5/TKR19701)	2012-034(10/12/TTK30601)
2011-182(10/5/TPK33301)	2012-051(11/1/ELM12301)
2011-182(10/5/TTK30601)	2012-051(11/1/GMM08001)
2011-182(10/5/WHK32101)	2012-051(11/1/GTH11301)
2011-182(10/5/WTR12001)	2012-051(11/1/IGW11901)
2011-228(10/6/ELM12301)	2012-051(11/1/KPA12401)
2011-228(10/6/GTH11301)	2012-051(11/1/OKU16701)
2011-228(10/6/HWA20801)	2012-051(11/1/OPO32001)
2011-228(10/6/IGW11901)	2012-051(11/1/PTA20901)
2011-228(10/6/KAW04405)	2012-051(11/1/PTR32601)

	2011-228(10/6/KPA12401) 2011-228(10/6/OKU16701) 2011-228(10/6/OPO32001) 2011-228(10/6/PTA20901) 2011-228(10/6/STR10201) 2011-228(10/6/TAU07001)	2012-051(11/1/STR10201) 2012-051(11/1/TKR19701) 2012-051(11/1/TPK33301) 2012-051(11/1/TTK30601) 2012-051(11/1/WHK32101) 2012-051(11/1/WTR12001)
Date of receipt:	Various dates from February 2011 to March 2012	
Name of reporting entity:	Allocation Agent	
Name of participant that is alleged to have breached the Rules:	Bay of Plenty Energy Limited	
Rule/s allegedly breached:	Gas (Downstream Reconciliation) Rules 2008 Rule 37.2	
Determination made by Market Administrator under regulation 18:	<p>In the Market Administrator's opinion the alleged breaches do not raise material issues and the Market Administrator has decided to take no action on the alleged breaches.</p> <p>The Market Administrator placed particular weight on the following criteria in making its determination:</p> <ul style="list-style-type: none"> • regulation 19(1)(a) – the alleged breaches were not severe • regulation 19(1)(o) – the alleged breaches involve gas volume differences within the threshold specified in "Market Administrator Guideline note rule 37 – materiality of rule 37.2 breaches (Downstream Reconciliation)" 	